



Fire Risk assessment bulletin update February 2020

In the event that post your FRA you replace or change the floor coverings in your building, and this subsequently affects the performance of your fire doors i.e. there is a gap at the bottom that will allow smoke to escape then you will need to re-engage with your fire door partner to have the doors adjusted (where possible) to ensure your doors meet the needs of the protection and remain compliant under BS 476-22.

If in doubt discuss with your accredited door support partner before undertaking any of this work

**Fire Alarm | Risk Assessment | Insurance Liaison | Emergency/Escape Lighting | Voice Evacuation
Refuge & Disability Systems | Kitchen Suppression Design | High Quality Labour Supply
Installation & Commissioning with BAFE Certification**



Graduate of the Institute of Fire Engineers GFireE | Member of the Institute of Fire Safety Managers IFSM
Support partner of Jactone for their LPS 1223 Kitchen Suppression system and LPS 1666 Electrical Enclosure suppression systems.
Veritas is proud to be working with certified contractors under the BM Trada Q-Mark fire door Maintenance & Installation scheme.